

# Paper Machine Dryer Gearing




FIG. 33.—Cloth-drying Machine.

## **AGENDA**

Intro to Paper Machine Dryer Gears

Gear Tooth Form

Gear Center Distance: Backlash & Tip/Root


Paper Machine Conditions Affecting Dryer Gearing

Wear Conditions

Inspection of Dryer Gearing

Lubrication


# Paper Machine Dryer Gearing




# Paper Machine Dryer Gearing

Open type cast iron spur gears were the common dryer section drive systems in paper machines up through the 1960's.

Many were later converted to use a combination of cast iron and nylon gears. This reduces vibration, noise, and eliminates the need for lubrication.




# Paper Machine Dryer Gearing





# Paper Machine Dryer Gearing

## Open Spur Gear Arrangements



Typical Horizontal Dryer Arrangement




Black Clawson Stacked Dryer Arrangement

# Paper Machine Dryer Gearing

As paper machine speed and widths increased, a gear arrangement with greater torque capacity became necessary.

Paper machinery builders began offering enclosed dryer gear cases with helical gears.


Due to the increased torque capacity of the helical tooth form, gear size could be reduced, simplifying and reducing manufacturing cost.




# Paper Machine Dryer Gearing

## Helical Gear Arrangements


**Beloit Style**



**Valmet & Tampella Style**




**Black Clawson Style**





# Paper Machine Dryer Gearing



A good tooth profile and good backlash equals smooth operation. Gear teeth have a curved (involute) surface to “roll” as they contact each other. When the involute curve is gone, the gears slide and vibration increases.

# Paper Machine Dryer Gearing

The angled teeth engage more gradually than do spur gear teeth, causing them to run more smoothly and quietly. Each pair of teeth first make contact at a single point at one side of the gear wheel; a moving curve of contact then grows gradually across the tooth face to a maximum then recedes until the teeth break contact at a single point on the opposite side.



# Paper Machine Dryer Gearing





Photo showing stress areas of gear tooth.


# Paper Machine Dryer Gearing



**Photoelastic study of mating teeth indicates the shift of the zero-stress point during crack propagation until final fracture reaches the opposite root radius. At the same time, deflection of the tooth allowed the adjacent tooth to pick up the load.**


# Paper Machine Dryer Gearing

**Backlash**, a clearance between mating **gear** teeth, is built into to let the gears mesh without binding and to provide space for a film of lubricating oil or grease between the teeth.



# Paper Machine Dryer Gearing

When gears have the proper profile and backlash, they roll together smoothly.



**NORMAL BACKLASH**


# Paper Machine Dryer Gearing



Older paper machine helical gear mesh with fair to good tooth profiles, and good backlash.

# Paper Machine Dryer Gearing

**Excessive backlash increases the “moment arm” distance between the tooth tip and root. This increases the stress on the gear. This increased stress is transmitted by a narrower (weaker) section of the tooth**



**EXCESSIVE BACKLASH**



# Paper Machine Dryer Gearing

## Excessive Spur Gear Backlash




# Paper Machine Dryer Gearing

## Excessive Helical Gear Backlash




# Paper Machine Dryer Gearing

Excessive Helical Gear Backlash Creating Overload



# Paper Machine Dryer Gearing

**When gears have tight backlash, they do not “roll” properly. The tips of the teeth will wear against the back-side of the mating teeth.**




**TIGHT BACKLASH**

# Paper Machine Dryer Gearing

Tight backlash  
with potential  
tooth tip to  
flank contact.



## TIP to ROOT CLEARANCE



## Causes of Change to Tip/Root & Backlash

### Spur Gears

- Loss of tooth thickness
- Shifted bearing housing(s)
- Worn or failed bearing
- Shifted or settling frame(s)

### Helical Gears

- Loss of tooth thickness
- Worn or failed bearing
- Shifted or settling frame(s)

## **Detrimental Paper Machine Conditions**

- Overdrive
- Backdrive
- Dryer Flooding
- Hard starting/stopping
- Lubrication Problems
- Misalignment



## **OVERDRIVE & BACKDRIVE**


Backdrive is when a driven gear is instead driving its input gear: the gear teeth are meshing on the normally unloaded side. For every backdrive condition, an overdrive condition also exists.

Often caused by excessive draw between sections: the sheet in the downstream section exerts a pull on the previous section. This pull is transferred by the sheet to the previous section dryers, and their gears. This overdrive pull may extend through the section.

This can also occur due to variations in dryer can diameter, which equates to a surface speed variation.

Areas where gears have been removed leaving the dryer(s) to be driven by the sheet and/or felt will result in overdrive and backdrive as the felt transfers the torque throughout the section, not just the ungeared dryers.

## DRYER FLOODING



A single flooded dryer can increase the torque load of the entire section by 40% or more.


## DRYER FLOODING

The increased torque load due to dryer flooding increases the gear tooth load, and wear. The extreme wear of the gear in the photo occurred within days of two dryers in the section flooding. All of the gears in the section were affected

The dryers will typically surge when flooded as the water inside cascades from side to side, accelerating and decelerating the dryer. The surging will affect and can be heard in the gear meshes. In open gears, the surging can be observed with a strobe light: the backlash will shift from one side of the teeth to the other as the dryer speeds-up and slows down.



## HARD STARTING & STOPPING



# Paper Machine Dryer Gearing

Other Conditions: Misalignment



# Paper Machine Dryer Gearing

Other Conditions: Offset Wear due Misalignment



## Wear Created by Poor Lubrication

**ABRAVISE WEAR:** Radial grooving and tearing along the tooth flanks.

**SCORING:** Radial scratching and grooving along the tooth flanks. Break down of the lube film at the point of contact and subsequent localized heating overheating create instantaneous welding and tearing out of material. Scoring can progress to pitting.

**PITTING:** typically occur in areas of high load concentration, often near the pitch line. They have an inverted cone shape; start small and become progressively larger. Can progress to Destructive Pitting, and Spalling, and ultimately lead to tooth failure.

**SPALLING:** Similar and often caused by Destructive Pitting, the voids are large and irregular in shape and cover a large area. Caused by high tooth stress and sliding action. Tooth failure probable as Spalling progresses.


**RIPPLING:** A cold flow surface deformation. Caused by high contact stresses and sliding action with attendant lube film breakdown.

**PEENING:** A cold flow surface deformation similar to but more severe than Rippling. Results in battered looking cold worked surfaces wear. Also caused by high loads and sliding action.

**FOREIGN MATTER DAMAGE:** An overload failure from contaminants passing through the gear mesh causing indentations, chipping, breakage or complete failure.

# Paper Machine Dryer Gearing

**Fine polishing is the removal of asperities on the gear surface during the break-in period. With good lubrication, polishing ends when the high spots have been worn down.**



**It's important to flush the oil system after running in new gears to flush the asperities out. Otherwise they become work hardened and act as abrasives.**



# Paper Machine Dryer Gearing


**Abrasive wear  
(and scoring).  
Typically  
caused  
by lubrication  
failure at gear  
mesh and/or  
particulate in  
the lube.**

**Will progress to  
destructive  
wear if not  
corrected.**




# Paper Machine Dryer Gearing

**Scoring is the instantaneous welding and tearing of contacting surfaces caused by localized overheating resulting from lube film breakdown.**




## Progress of Wear

### PROFILE WEAR




## **ABRASIVE WEAR & SCORING W/LOSS of PROFILE**



## PITTING & SPALLING

**Occurs when the load exceeds the capacity of the gear material and/or the lube film thickness is inadequate. The repetition of high stress over many cycles produces surface & subsurface stressers. The material fatigues and fails either at or below the surface. The crack(s) then propagate to the surface and a small piece breaks free forming a pit. If not corrected, many smaller pits join to create larger craters called Spalls.**



Pitting is often the first indication of a lube film problem caused by high temperature.

# Paper Machine Dryer Gearing

## Abrasion with Pitting and Spalling Below the Pitch Line

**Inadequate lubrication creates a condition wherein high points on the gear surface contact causing high stressers resulting in pitting.**



# Paper Machine Dryer Gearing

## Destructive Pitting



Tooth failure may occur where pitting is destructive due to the loss of tooth material and strength.

# Paper Machine Dryer Gearing




The teeth in this dryer gear have failed due to loss of tooth material at the pitch line caused by destructive gear wear (destructive pitting and spalling).



# Paper Machine Dryer Gearing

## Foreign Matter Damage



# Paper Machine Dryer Gearing

## Foreign Matter Damage



## Gear Inspection

### Spur Gears

- Dynamic via strobe light
- Visual: tooth form, wear modes & severity, damage, alignment
- Backlash measurement
- Tooth thickness measurement






# Paper Machine Dryer Gearing

## Inspection Drawing Detail

### 5TH SECTION UNFELTED



# Paper Machine Dryer Gearing

## Inspection Drawing Gear Data & Notes


DRYER GEARING - 116 T, 2.00 DP, 20 PA, STD. FULL DEPTH, 6.00" FACE  
 RECOMMENDED BACKLASH .040-.060  
 STD. TOOTH THICKNESS .760  
 (WITH BACKLASH ALLOWANCE)  
 ADDENDUM .500  
 PTS PART NO, #5116061.0001  
 PART NO, ON GEARS #02114-000, 052184-000

DRIVE PINIONS - 62 TOOTH 2.00 DP 20 PA 6.00" FACE  
 PART NO, ON GEARS #


NOTES

- 1.) PROBABLE TIGHT CENTERS: #4/#5, #35/#36, #39/#40, #40/#41, #44/#45, #50/D-5, #54/#55, #58/#59, #61/#62, #62/#63, #65/#66, #70/#71, #72/#73, #73/#74
- 2.) PROBABLE SPREAD CENTERS: #6/D-1, #45/#46, #49/#50, #50/#51, D-5/#52, #53/#54, #57/#58, #66/#67, #68/#69, #69/#70, #71/#72, #76/#77
- 3.) PTS REFILLED GEARS
- 4.) PTS REFILLED CONVERSION GEARS
- 5.) GEARS MANUFACTURED BY OTHERS
- 6.) NO BACKLASH READINGS - GUARDS IN PLACE
- 7.) GEARS REVERSED-SET SCREW ON TENDING SIDE OF GEAR
- 8.) GEARS WITH NO SET SCREW
- 9.) GEAR OVER PINION - DOUBLE CONTACT
- 10.) GEARS REMOVED FOR REPAIRS
- 11.) CHECK FOR SET SCREW
- 12.) DAMAGE TO NYLON GEAR FROM WORN CI GEAR
- 13.) BROKEN BOLTS REPLACED WITH IMPROPER HARDWARE
- 14.) 2-1/2" AREA WORN ON TOP OF GEAR LANDING
- 15.) SCORING ON C.I. GEARS - PREMATURE WEAR ON NYLON
- 16.) DAMAGE TO LANDING OF DRIVE GEAR

REPLACEMENT RECOMMENDED




OVER .060"  
REDUCTION



OVER .100"  
REDUCTION




INSUFFICIENT  
BACKLASH



EXCESSIVE  
BACKLASH

# Paper Machine Dryer Gearing

## Inspection Drawing Notes



## Gear Inspection

### Helical Gears

- Visual: tooth form, wear modes & severity, damage, alignment
- Backlash measurement (not all cases have suitable access ports)
- Video scope








# Paper Machine Dryer Gearing

## Inspection Drawing: Helical Gears



# Paper Machine Dryer Gearing

## Internal Gear Case Pics via Video Scope



Video Scope Photo. Note concentrated loading on one side of the gear teeth. Indicates a misalignment condition.




Video Scope Photo. Note cold flow of tooth edge; probably from contact with foreign matter.

Many of the photos of helical gears in this presentation were taken using the Video Scope. We also use this instrument for inspection of gearbox internals, and other mill components that lack good visual inspection access.

# Paper Machine Dryer Gearing

## Inspection Drawing Detail

5TH SECTION  
UNI-RUN FELTED



April 01, 2015 Inspection

# Paper Machine Dryer Gearing

## Inspection Drawing Notes

### NOTES:



- 1.) Slight front tooth edge rolling and chipping.
- 2.) Moderate front tooth edge rolling and chipping.
- 3.) Significant front tooth edge rolling and chipping.
- 4.) Tooth landing damage.
- 5.) Heavy Spalling-Drive Side
- 6.) Possible Cracked Weld
- 7.) Side Scoring/Rubbing
- 8.) Point Loading/Possible Bad Bearing
- 9.) Gear Face Misalignment Idler 121/Dryer#13
- 10.) Change In Wear Pattern
- 11.) Machined Bearing Ft.
- 12.) Gears Replaced in 7/14
- 13.) Replaced Bearings
- 14.) Heavy Pitting Above the Addendum.

# Paper Machine Dryer Gearing

## Inspection Drawing Gear Data


**GEARING:**

8 MP, 5.31" FACE  
 STANDARD TOOTH THICKNESS .737"  
 (WITH BACKLASH ALLOWANCE)  
 RECOMMENDED BACKLASH .030" - .040"  
 ADDENDUM .469"




## EFFECT OF LUBE FILM THICKNESS

If lube film thickness is inadequate, asperities in the gear tooth surface contact creating wear (and wear particles).



## OIL JET IMPINGEMENT

The optimum condition is obtained when the lubricating oil is directed perpendicular to the tooth tip at a velocity equal to the tooth pitch-line velocity.



## **LUBE IMPINGEMENT VELOCITY**

**TAPPI tip #0420-08 suggests a flow rate of 2 pints (.125 gal)/minute/gear mesh supplied through 1/2" NPT ports. Under these conditions, the oil obtains a velocity of 0.2 feet/second.**

**The case study paper machine has a gear pitch-line velocity of 35 feet/second (175 times faster than the oil velocity in the above recommendation).**



**Under these conditions, most of the oil will be deflected by the tooth tips and little will reach the tooth flanks where it is most required.**

**With the oil deflected by the tooth tips, it has little chance of being transported to the working depth of adjacent gears.**

**Lube velocity is equally important to flow. Flow alone will not provide good lubrication in paper machine dryer section gears.**



# *Paper Machinery*



*From Stock Prep to Finishing*